



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
November 7, 2005

Supervisor DRH

Mine Name: Lone Pine Quarry
Operator Name: Barry Petersen / Gold Star Stone, Inc.

Permit number: M/003/050

Inspection Date: Nov. 1, 2005

Time: 4:30 pm

Inspector(s): Lynn Kunzler, DOGM

Other Participants: none

Mine Status: Active

Weather: Cold, Cloudy, Windy

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This inspection was done while in the area.

Inspection Summary:

- 1 & 5. The operator had recently received tentative approval for a 2-acre amendment to his operation. On September 12, 2005 the Division notified the operator that his business license with the Dept. of Commerce had expired and that he needed to renew this license before the Division could issue final approval. While traveling to an adjacent operation, it was noted that a new road had been constructed in the vicinity of this amendment.

During the inspection, it was noted that the new quarry was not developed at the location shown on the permit map (or where the operator had indicated it would be to the inspector during an inspection on May 25, 2005). A new road (cut and fill) had been constructed as well - (the amendment showed using an existing two-track road). The quarry area and the new road were surveyed using a GPS unit to determine location and size of the new disturbances.

Conclusions and Recommendations:

Results of the GPS survey show the new quarry area to be 2.08 acres in size, and the access road to be 0.85 acres. This is 0.85 acres larger than the pending amendment. Other than about 0.2 acres of the road disturbance, all of this new disturbance is outside the area of the

Inspection Date: November 1, 2005; Report Date: November 7, 2005

Page 2 of 2


M/003/050

proposed amendment. A violation needs to be issued for conducting operations outside the permitted and bonded area.

While the mine status was marked as active, this operation has closed down for the winter (probably within the last week or two).

Photos were taken to document site conditions.

Inspector's Signature



Date: November 7, 2005

LK:jb

O:\M003-BoxElder\M0030050-LonePine\inspections\insp-11-1-2005.doc